

ERRATUM:

Vakili-Farahani, F., Amalfi, R. L., and Thome J. R., Two-Phase Flow and Boiling of R245FA in a 1 mm Pressing Depth Plate Heat Exchanger —Part I: Adiabatic Pressure Drop, *Interfacial Phenomena Heat Transfer*, vol. 2, no. 4, pp. 325–342, 2014.

On page 341, Fig. 12, parts 12c and 12d were missing from the original published article. Below is the complete correct figure. The online version of the article has been corrected.




FIG. 12: Two-phase adiabatic test results at $G = 10 \text{ kg s}^{-1} \text{ m}^{-2}$, $T_{sat} = 30^\circ \text{ C}$, and $x = 0.57$ (a) measured temperature by IR camera (b) refrigerant pressure field obtained from IR measurements (c) widthwise pressure profiles (d) lengthwise pressure profiles